



To all purchasers of recent RX1/2 kits.

Please note: Some of the newly arrived knobs are a bit tight on the control shafts.

Both shafts and knobs are $\frac{1}{4}$ " (6.35mm) but we have found that the a lip from the tapped 4mm grub screws makes the shafts a tight fit. In some cases, the actual brass insert is slightly less than $\frac{1}{4}$ " but only by a very small amount.

This can be fixed by lightly running a small Dremel grindstone inside the brass section of the knob. A $\frac{1}{4}$ " drill or end mill turned by means of a pair of thick pliers also may work.

Try the shafts in the knobs to test the tightness before assembling the kit.

Also, remember to retract or remove the grub screw first to ensure you are cleaning up the edge of the tapped hole and not fouling the grub screw.

Thank you,
Lou,
VK3AQZ
15-12-2012

